COVER PAGE

EXCELLENCE IN LEADERSHIP ACADEMY SEEKS RESPONSES TO:

Request for Quotation(s) Number: RFQ-01312020-16073417-CAB

for

E-Rate Calbing Services

for

E-Rate Funding Year 2020

IMPORTANT

Proposers must be able to offer pricing through DIR, TCPN, or other District approved cooperative purchasing organizations

DISTRICT INFORMATION

Excellence in Leadership Academy 915 W. Interstate Hwy 2 Mission, TX 78572

Billed Entity Number: 16073417

IMPORTANT DATES

RFQ Issued: Friday, January, 31, 2020

Walkthrough: 01:00 PM CST on Friday, February, 07, 2020

RFQ Questions Due: 05:00 PM CST on Friday, February, 14, 2020

RFP Closes: 03:30 PM CST on Monday, March, 02, 2020

*** Items received after the specified Dates and Times will not be considered ***

Questions and responses must be sent electronically to:

calfaro@elacharterschool.com

and

mailto:astone@vstservices.com

Walkthrough Location

915 W. Interstate Hwy 2 Mission, TX 78572

COVER PAGE

PROPOSER INSTRUCTIONS

PLEASE READ ALL INSTRUCTIONS CAREFULLY

Worksheets (tabs) for campus proposals are shown in *Yellow* and have the *School Name* and *Entity Number* on them.

RESPONDING TO THE WORKSHEETS

Worksheets:

Proposer Info (Fill this out completely, sign, scan and email this to the address on the page)

Cover Page (No response required, please read thoroughly) **Evaluation** (No response required, informational only)

Cost Summary (A running cost summary of your proposal response)

Remaining Worksheets

The remaining worksheets represent each site that requires Category 2 Goods and/or Services. Please reply to each worksheet. Any items not replied to will be considered non-response.

- 1. Click on each worksheet and review the items requested.
- 2. For each item that contains a *Manufacturer Part Number*, *Description* and *Quantity*, respond by adding a *Proposer Part Number*, *Cost* and state what % of the *Product is Eligible*.
- 3. If you are offering an alternate to the solution requested, be sure to fill in the *Equiv* column with a "Y" to indicate that the product is an alternate.
- 4. Complete all worksheets that request pricing. Any incomplete items will be considered non-responsive.

Note: Within each worksheet, these columns are colored **GREEN** for easy identification.

RETURNING YOUR RESPONSE

When you have completed pricing all requested items, please save and then e-mail this workbook back astone@vstservices.com.

PROPOSER INFORMATION

Company Information

Company Name:				
Street Address:				
City:		State:	Zip:	
USAC SPIN Number:		Submittal Date	e:	
Sales Contact Informa	ation			
Primary Contact:		Title:		
Phone:		E-Mail:		
		State:	Zip:	
State Contract or Inte	erlocal Agreement Information	on		
Please provi Rate Calbing	de all relevant state contract Services.	numbers. These shou	ıld be a valid contract for E-	
0	rganization Name	Contract Number	Expires	

Instructions: Sign and Date this page, then scan and email it to: astone@vstservices.com

Signature Date

Proposer Signature

SUMMARY

Excellence in Leadership Academy 2020 E-Rate - Request for Quotation(s)

Location Name	Campus Total
Exel in Lship-16073417	-
Total Cost:	-

Note: This page is automatically calculated. Please do not change anything on this sheet

PRICING RESPONSE FOR:

EXEL IN LSHIP-16073417

915 W EXPRESSWAY 83 MISSION, TX 78572

Part Numbers			Equiv	Pricing Information			
Manufacturer PN	Proposer PN	Description - As specified or equivalent. If equivalent, please place a "Y" in this column>	(Y/N)	Qty	Cost	Extended	% Elig
SR42UBEXPNDNR3		Tripp Lite 42U 4-Post Open Frame Rack Cabkinet Square Hole Heavy Duty Cater rack		1		-	
N252-048		48-Port 2U Rack-Mount Cat6/Cat5 110 Patch Panel, 568B, RJ45 Ethernet, TAA		2		-	
N252-024		24-Port 1U Rack-Mount Cat6/Cat5 110 Patch Panel, 568B, RJ45 Ethernet, TAA		1		-	
N238-001-BL		Cat6/Cat5e 110 Style Punch Down Keystone Jack - Blue, TAA		120		-	
		Cable Ladder (Horizontal and Vertical appx 20 ft) to support approxiamtely 100 Cables				-	
		Grounding Busbar				-	
		#6 Ground wire (to connect grounding to building red-iron appx 50 ft)				-	
						-	
						-	
		Labor cost for the following:				-	
		1. Remove existing rack in the MDF, including patch panels and equipment				-	
		2. Install rack, ladder, grounding busbar, ground wire to red iron and ground rack and ladder per code				-	
		3. Install new patch panels				-	
		4. Remove and reterminate existing cabling (approximately 100 cables) in new patch panels				-	
		5. Properly label patch panel and workstation outlet to match and document				-	
		6. Recertify cabling				-	
						-	
		Deliverables				-	
		1. Receritification test documentation (Provide test results to match labeling in electronic format)				-	
		2. Update as-built documentation (Provide in PDF format)				-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	

PRICING RESPONSE FOR:

EXEL IN LSHIP-16073417

915 W EXPRESSWAY 83 MISSION, TX 78572

Part Numbers			Equiv		Pricing In	formation	
Manufacturer PN	Proposer PN	Description - As specified or equivalent. If equivalent, please place a "Y" in this column>	(Y/N)	Qty	Cost	Extended	% Elig
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						-	

PRICING RESPONSE FOR:

EXEL IN LSHIP-16073417

915 W EXPRESSWAY 83 MISSION, TX 78572

Part Nu	mbers		Equiv		Pricing In	formation	
Manufacturer PN	Proposer PN	Description - As specified or equivalent. If equivalent, please place a "Y" in this column>	(Y/N)	Qty	Cost	Extended	% Elig
						-	
						-	
						-	
						-	
						-	
						-	
						-	
						ı	
						-	
						ı	
						-	
						-	
						-	
						-	
						-	

_	
EXEL IN LSHIP-16073417 TOTAL COST	-